

KEITH PRODUCTS, L.P. ENVIRONMENTAL SYSTEMS

CERTIFICATION REPORT NO. CR-400-9 AIR CONDITIONING/HEATING SYSTEM INSTALLATION

FLIGHT MANUAL SUPPLEMENT

FOR

CESSNA MODELS: 402B/402C/414/414A/414B/421C

STC NO. SA8RM

Date:

February 21, 1973

Rev:

Rev. Date: October 5, 1982

FAA APPROVED

AIRPLANE FLIGHT MANUAL SUPPLEMENT

FOR

CESSNA MODELS: 4028, S/N 40280301 and up 414, S/N 414-0351 and up 414A, 421B, 402C - all S/N's 421C - all S/N's (6,7,8,9,10 seat)

| Registration | No. | |
|--------------|-----|--|
| Serial No | | |

This supplement is part of the FAA approved operating limitations and must be carried in the aircraft when an airconditioning system is installed in accordance with STC SA8RM. The information contained herein supplements or supersedes the basic data only in those areas specified. For limitations, procedures, and performance information not contained in this supplement, consult the original approved manual material, markings, and placards.

| I. | LIMITATIONS | Page 2 |
|------|----------------------|--------|
| II. | EMERGENCY PROCEDURES | Page 2 |
| III. | NORMAL PROCEDURES | Page 2 |
| TV | DEDECOMANCE | Page 2 |

FAA APPROVED

Gueld E. Lendblood

DATED February 21, 1973

GERALD E. GOODBLOOD, Chief Engineering and Manufacturing Branch ARM-210

Page 1 of 3

Revision D

| T | | ı | T | M | T | 7 | ٨ | т | T | ONS | |
|---|---|---|---|-----|---|----|---|---|---|------|---|
| Ŧ | • | L | Ļ | ı'ı | À | 1. | ^ | | ٠ | 0117 | • |

Placard on Instrument Panel:

TURN AIRCONDITIONER OFF FOR T/O AND LANDING.

II. EMERGENCY PROCEDURES:

In the event of alternator failure, turn off airconditioner.

III. NORMAL PROCEDURES:

Airconditioning system operation. The airconditioning switch is located on the pilot's instrument panel.

Turn airconditioner off - when performing alternator checks.

To turn airconditioner ON - Move switch to 'AIRCONDITIONER'.

To turn airconditioner OFF - Move switch to 'OFF'.

For circulation without cooling - Move switch to 'FAN ONLY'.

IV. PERFORMANCE:

No change.

FAA APPROVED

DATE February 21, 1973

REVISION _____D

Page 2 of 3

| REVISION PAGES | | 0.0001071011 | FAA | | |
|----------------|-----|--------------|---|---------------|--|
| NUMBER | NO. | DATE | DESCRIPTION | APPROVED | |
| А | 1 | 9/24/79 | Added Model 402C and changed format. | J & all | |
| В | All | 1/22/80 | Revised to show correct orig. release date. | J. D. Clarky | |
| С | ATT | 2/4/81 | Revised to change company name. Added S/N to model callouts. | J. P. Charley | |
| D | 2 | 10/5/82 | Added: "Turn aircond. off when performing alternator checks." | J. P. Charle | |
| | | | | | |
| | | | , | | |
| | | | | | |
| | | | | | |

| FAA APPROVAL | Levell E. | Killes. | DATE_ | February | 21, | 1973 | | |
|--------------|-----------|---------|-------|----------|-----|--------|----|---|
| REVISION | D | | | | | Page 3 | of | 3 |